



| | | | | | |
|--|-------------------------|--------------------------------------|---|--------------------------------------|--|
| High Tech Computer Corporation Quality Capture Advisory | | | | DOC-00022273 | |
| Issue Date: 2006/10/19 | Revision: A01 | Affected P/N: 76H01398-00M | Description: Excalibur | Effective Date: 2006/10/19 | |
| Reasons: Excalibur Adhesive-Double Tape assembly notice item | | | | | |
| Areas Affected: () S/W Release () FRU Inventory (x) Parts Inventory () Documentation () Others | | Location: (x) WWW ASP | Service site: Engineer Leader Sign here: Implement Date: | | |
| All Related Personnel Sign here: | | | | | |
| Description of Change and Notice: In order to prevent touch sensor floating issue, rework Excalibur jog bar please change Adhesive-Double Tape (P/N 76H001398-00M) | | | | | |
|  | | | | | |
| Fig1. Adhesive-Double Tape (P/N 76H001398-00M) | | | | | |
|  | | | | | |
| Fig2. Mylar stick position | | | | | |

Remark : Capture program will stop when the HTC inform you again. **However, the capture may continue by any special case. Please pay attention.**

| | | |
|----------------------------------|----------------------------------|---|
| Originator: Edwin_Chen | Approved By: Henry_Lai | HTC Contact: Tel: 886-3-3753252 # 5937 E-Mail: edwin_chen@htc.com.tw |
|----------------------------------|----------------------------------|---|

- **Confidentiality:** *This document is permitted of the above assigned service partner for repair service and is confidential and/or legally privileged. Nor must you copy or show it to anyone without HTC's agreement.*
- **Sign back:** *Please have an internal short meeting to make sure all engineer and related personnel understand and catch the notice. Please confirm receiving of this SA via e-mail. Please do not use FAX on replying.*